Effective Estimating

BASF AUTOMOTIVE REFINISH COATINGS





















Glasurit

- *Introductions
- *Restrooms
- *Fire Exits









Anti-Trust Disclaimer

- Please be advised that the following guidelines for conduct shall be established and followed:
 - No participant shall be allowed to discuss any subject relating to prices charged, discounts offered of any nature, hourly rate, employee benefits, or assignments made with third party entities.
 - Should any discussion of these items take place, said participant will be asked to refrain immediately, disregarding any pursuant discussion, and should said party deny such request, the meeting will be immediately disbanded.
 - All participants are herewith notified that the materials presented herein are not to be construed as information or direction to take concerted actions.
 - The information can be utilized by individuals acting within their own judgment, making sound business decisions, without agreements with other participants of this meeting.
- This notice is hereby read with regard to laws governing this conduct.

Product Disclaimer: Products mentioned in this presentation are for information purposes only and do not represent an endorsement by BASF.










What is going on in this picture?











Vehicle Inspection





Inspect Vehicle with customer

- Develop a mutual understanding of vehicle condition
- Develop a mutual understanding of areas being repaired
- Develop a *mutual* understanding of pre-existing damage



Determine if an estimate is necessary

- Sell First
- Assess Damage Second











Vehicle Assessment

- Check for panel misalignment or deformity
- Check for loose joint and seam sealers
- Check for chipped paint













Verify Vehicle Information

- Make
- Model
- Trim Level Decoding
- Mileage
- **Production Date**
- **Exterior Color**
- Interior Trim Color









2017 GMC Sierra 2500 HD Denali Crew Cab 153.7" WB 4WD 4D P/U 8-6.6L Turbocharged Diesel Direct Injection white

1GT12UEY6HF231255 Interior Color: Mileage In: 9,363 Vehicle Out: 1/23/2018

NONE Exterior Color: white Mileage Out: License:

State: Production Date: 6/2017 Job #: jason Condition:

TRANSMISSION	CONVENIENCE	CD Player	Leather Seats
Automatic Transmission	Air Conditioning	Auxiliary Audio Connection	Heated Seats
Overdrive	Tilt Wheel	Premium Radio	Ventilated Seats
4 Wheel Drive	Cruise Control	SAFETY	WHEELS
POWER	Rear Defogger	Drivers Side Air Bag	20" Or Larger Wheels
Power Steering	Keyless Entry	Passenger Air Bag	PAINT
Power Brakes	Alarm	Anti-Lock Brakes (4)	Clear Coat Paint
Power Windows	Steering Wheel Touch Controls	4 Wheel Disc Brakes	OTHER
Power Locks	Telescopic Wheel	Traction Control	Fog Lamps
Power Mirrors	Climate Control	Stability Control	Signal Integrated Mirrors
Heated Mirrors	Navigation System	Front Side Impact Air Bags	TRUCK
Power Driver Seat	Backup Camera w/Parking Sensors	Head/Curtain Air Bags	Rear Step Bumper
Power Passenger Seat	Remote Starter	Communications System	Power Rear Window
Power Adjustable Pedals	Home Link	Hands Free Device	Bedliner (Spray On)
DECOR	RADIO	Xenon Headlamps	Trailer Hitch
Dual Mirrors	AM Radio	Positraction	Trailering Package









Verify Vehicle Options











Take Preliminary Photos

BEST PRACTICES GUIDELINES FOR DIGITAL IMAGING

The Collision Industry Conference Insurer-Insurance Relations Committee, a dedicated volunteer group of insurers, repairers, and industry partners has produced a set of working guidelines that represent a consensus on how to work together for the benefit of the vehicle owner using good faith business practices and mutual respect in the event of a collision or an event which results in the need for collision repair.

Now the members of the Collision Industry Conference ask that all responsible repairers and insurers endorse and adopt these common-sense practices.

NOTE: This is a "living" document, designed to be modular in approach. It is intended to be global in nature and will provide the framework for all collision industry Best Practices. This is a draft and is not intended to be acted upon in any way other than review and comment from interested industry colleagues.

- These guidelines describe only the basic imaging requirements needed on all vehicles. Other factors, such as severity, complexity, and individual insurer policies or requirements, may necessitate taking additional images or approaches.
- Taking the images of the damage should come after examining the vehicle to determine the point of impact, related and unrelated damage.
- 3. Basic Imaging Procedures
 - a. Take initial images to capture all four corners of the vehicle including the license plate.
 - Take images of the instrument panel, dash warning lights, (if possible, with engine running), odometer, and VIN plate, including vehicle production date.
 - c. Take images of all loss related damaged parts listed on the estimate. The sequence of the images should mirror the sequence in which the repair estimate was written. Remember to take establishing or overall images for context in addition to close ups.
 - d. Take images of all unrelated damage and label as such.
 - Review the images to ensure they are clear, well lit and fully depict the extent of damage to the vehicle. Delete and recapture any blurry, dark or unusable images.
- 4. Minimum Requirements
 - a. 4 Corner shots
 - i. Always try to include the License Plate in the photo



Reference CIC Best Practices

- Four Corners
- License Plate
- Instrument cluster
 - With engine running
 - Dash warning lights
 - Mileage
- VIN Plate















Review Repair Process



The Society of Collision Repair Spec services our technicians provide th: The purpose of this document is to the estimate preparation process, intended to be used as a guide to d as a reminder of steps that may be promote, that your shop can or sho repair operations that are perform

The document does not contain pri determined based on your facility's notified that the materials presente concerted actions. Information can

BASF AUTOMOTIVE REFINISH COATI






o



Visit www.scrs.com to become a member, or learn more about the Society of Collision Repair Specialists

Become familiar with damaged area

- Review the P-pages
- Learn what is included and what is not
- Check the H-notes
- Review SCRS Guide to Complete Repair Planning












Possible System Fault Areas











Pre-Scan Diagnostics

- Scan system to locate fault codes
 - Add diagnosis line to estimate
 - Place line under affected system
 - Separate diagnosis for each system





BULLETIN

FOR THE COLLISION REPAIR PROFESSIONAL

TITLE: Scanning for Electrical System Faults 2016-191

SECTION: Electrical Page 1 of 1

APPLICABLE VEHICLES: All Toyota, Lexus and Scion Models

TOYOTA @LEXUS +SCION



These electrical systems are designed to set fault codes known as DTCs (Diagnostic Trouble Codes) if a fault is detected. Not all DTCs illuminate a MIL (Malfunction Indicator Light). Toyota's "Techstream" and "Techstream Lite"* scan tool and software can retrieve and report all DTCs for all Toyota, Lexus, and Scion vehicles.**



repairers perform a "Health Check" diagnostic scan if a vehicle has sustained damage as a result of a collision that may affect electrical systems. Additionally, Toyota strongly recommends that repairers perform a "Health Check" diagnostic scan before and after every repair to identify and document DTCs. If DTCs are identified pre-repair, then they can be considered to create a complete vehicle damage analysis report. If DTCs are identified post-repair, then they can be diagnosed and addressed before returning a vehicle to the customer.





*Call Toyota Approved Dealer Equipment at 800.368.6787 for information, availability and pricing.

** Before using an aftermarket scan tool, check with the manufacturer to ensure that their equipment can retrieve History, Pending and Current DTCs as well as 'Time Stamp' their occurrence on all Toyota vehicles.










Advanced Driver Assistance Systems







Verify need for recalibration









Damage Review



- Begin reviewing damage
 - Start at end of vehicle with most damage
 - Work with the body technician to identify repairs needed
 - Work panel by panel to opposite end of vehicle



Remove/Install

LT Mudguard







LABOR UNITS

BASF AUTOMOTIVE REFINISH COATINGS

Document Exterior Damage

MATERIAL SUBLET PRICE

- Begin documenting major assemblies damaged
- Allow the estimating system to work for you

			6-7				C	01 - FRONT AND REAR BUMPERS:	
		• Doc	ument repair front to	real	or re	ar to front	+ 1	. FEATHERFILL, SAND AND BLOCK REPAIR AREA	
		DOC	amenerepair none to	i Cai	OI I C		2	. REMOVE BUMPER MOLDING ADHESIVE	
1	E01		FRONT BUMPER				3	. DRILL FOR LICENSE PLATE	
2	E01	Remove/Replace	O/H front bumper				2.4	. R&I LICENSE PLATE	
			' '				5	. LICENSE PLATE, REPAIR	
3	E01	Remove/Replace	Bumper cover	1	245.00T	Opt OEM	0.0		
			NOTE: Price matched with OEM part				7	. CCC BUMPER PROMPT *ADD BACK OVERLAP + CLEAR*	
4	E01		Add for Three Stage				8	. R&I FOG LAMPS	
5	E01	Remove/Replace	LT Lower bracket	1	8.75T	OEM	9	. R&I TRAILER HITCH (ON BUMPER)	
-								0. AIM FOG LAMPS	
6	E01	Remove/Replace	LT Corner support	1	5.95T	OEM		1. R&I CAMERA AND WIRING	
7	E01	Remove/Replace	RT Corner support	1	5.95T	OEM	0.1	2. TRIAL FIT BUMPER	
8	E01	Refinish	Tow eye cap				_	R&I TRAILER HITCH (FRAME BOLT-ON TYPE) R&I OR R&R SENSORS (SRS-AMBEINT TEMP- ETC)	
		TO THIS IT	, .				_	5. REPAIR BUMPER BRACKET AND/OR OTHER COMPONENTS	
9	E01		Add for Three Stage					6. REPAIR BUMPER BRACKET MOUNT AREA	
10	E01		GRILLE				_	7. REPAIR BOMPER BRACKET MOONT AREA	
11	E01	Remove/Install	R&I grille assy					8. REFINISH O.E.M "RAW" BUMPER	
12	E01		FRONT LAMPS					9. REFINISH, SECOND COLOR ON BUMPER COVER	
		- /					2	REFINISH, BLACK-OUT ON BUMPER COVER	
13	E01	Remove/Install	LT Headlamp assy				0.0	1. PAINT PREP & CLEAN UP USED BUMPER	
14	E01		FENDER				2	2. MASK UNPAINTED AREAS ON BUMPER COVER	
15	E01	Remove/Replace	LT Fender	1	225.00T	Opt OEM		3. MASK BUMPER COVER FOR PRIMER APPLICATION	
16	E01	, ,	Add for Three Stage				2	4. FLEXIBLE PARTS ADHESION PROMOTOR APPLICATION	
			•				2	5. REPLACE MINI BULBS	
17	E01		Add for Edging					6. RAW BUMPER PREP KIT	
18	E01	Remove/Replace	LT Fender liner	1	60.53T	OEM	0.0	7. BUMPER FASTENERS/RETAINERS (KIT)	
19	E01	Remove/Install	LT Filler trim					URETHANE BUMPER REPAIR KIT (MATERIALS) FLEXIBLE PARTS ADDITIVE	
20	E01	Remove/Replace	LT Wheel flare	1	126.38T	OEM	0.0		
		, ,	LT Pillar cover	-			0.0	Society of Collision Repair Specialists • P.O. Box 909, Prosser, WA 99350 • (877) 841-0	660 • Fax (877) 851-0660
21	E01	Remove/Install	Li Filiai Cover				0.0		

0.2T Body

DESCRIPTION










Identify R&I Requirements



- Determine R&I's for repair access
 - Headlamps
 - Mounting brackets
 - Windows

- Determine R&I's for paint access
 - Door handles
 - Weather strips
 - Fender liners









Document Access Labor

Document additional labor to access damage

- Add as a line item on estimate
 - Show labor within area being repaired
 - Create a line note explaining addition

39	E01		QUARTER PANEL					
40	E01	Blend	LT Quarter panel					1.6T
41	E01	Remove/Replace	LT Quarter panel protector	1	16.06T	OEM	0.2T Body	
42	E01	Repair	LT Quarter glass Toyota (Backtape for refinish)					0.5T
43	E01		REAR LAMPS					
44	E01	Remove/Install	LT R&I tail lamp				0.3T Body	
45	E01		REAR BUMPER					
46	S01	Remove/Install	R&I bumper assy				0.5T Body	










Identify Measurement Needs

- Establish need for measurements
 - Is there sway?
 - Are gaps misaligned?
 - Does a door drag on the striker?
 - Do you see a frame buckle?
 - Are body panels distorted?
 - Is there suspension damage?

135 - FRAME SET UP:	
684. UNIBODY CLAMP SYSTEM	
685. FULL FRAME CLAMP SYSTEM	
686. NON-DRIVE VEHICLE (NO START)	
687. DISABLE VEHICLE (DOES NOT ROLL)	
688. LIFTED/LOWERED VEHICLE	
689. TRAM VEHICLE TO DETERMINE IF MOVEMENT EXISTS	
690. INSTALL MECHANICAL MEASURING SYSTEM	
691. ELECTRONIC MEASUREMENT DOCUMENT	SCRS
692. R&I ROCKER MLDGS- ACCESS TO CLAMP AREA	REPAIRER DRIVEN
693. ACCESS PULLING TO FACILITATE TEAR DOWN	
694. R&I INTERFERING WIRES, TUBING/LINES, EXHAUST	
695. R&I SUSPENSION/STEERING, PARTIAL	
696. REPAIR CLAMP SCARING ON ROCKER FLANGE	
697. REPAIR ANCHOR DAMAGE AT LOCKING POINTS	<u> </u>
698. REPAIR PROTECTIVE COATING AT ROCKER	<u> </u>
699. PAINT ROCKER FLANGE	



Document need for measurement of torque box and four corner points










Inspect Inner Structure

Visually Check for structural damage





Pay particular attention to crush zones










Understanding Inner Structure

- Review structure composition
 - Check to determine steel type and reparability













Evaluate Structure Repair

- Determine reparability
 - Identify sectioning processes
 - Review OEM websites
 - Review I-CAR guidelines
- Document SIR disabling requirement
- Document Battery disconnect requirement




Front Full Frame Sectioning (Heavy Duty)

Removal Procedure

If damage permits a pre-sleeved replacement front frame service section has been developed as a cost-effective alternative to complete frame replacement. This procedure is for the heavy duty pick-up front frame service section.

WARNING: Refer to <u>Approved Equipment for Collision</u> <u>Repair Warning</u>.



WARNING: Refer to <u>Collision Sectioning Warning</u>. **NOTE:** Perform all of the steps on both of the rails for complete module replacement.

- Disable the SIR system. Refer to <u>SIR Disabling and</u> Enabling.
- Disconnect the negative battery cable. Refer to <u>Battery</u> <u>Negative Cable Disconnection and Connection</u>.
- 3. Remove all of the related panels and components.









Document Structure Repair

- Itemize each repair required
 - Separate each panel
 - Core Support
 - Apron
 - Lower Rail

15 - CORESUPPORT:	
70. ACCESS/PRE-PULLING	CCDC
71. PROTECT ENGINE COMPARMENT COMPONENTS	SEPARER CRIVEN
72. REPAIR CUT WIRING	
25 - APRON/UPPER RAIL:	
136. PRE-PULL/ACCESS	CCRC
137. REMOVE CAULKING & SEAM SEALER	REPAIRER DRIVEN
138. REPLACE CAULKING AND SEAM SEALER (NEW PART)	
145 - FRONT END DAMAGE:	
799. PRE-PULL TO FACILITATE TEAR DOWN	
800. PULL & REPOSITION CORESUPPORT	
801. REPAIR FRONT BUMPER WELDED MOUNTING BRACKE	T (EACH)
802. CORRECT UPPER RAIL/APRON SWAY, LEFT	
803. CORRECT UPPER RAIL/APRON SWAY, RIGHT	CCDC
804. CORRECT UPPER RAIL/APRON HEIGHT, LEFT	
805. CORRECT UPPER RAIL/APRON HEIGHT, RIGHT	REPAIRER DRIVEN
806. CORRECT UPPER RAIL APRON LENGTH/MASH, LEFT	
807. CORRECT UPPER RAIL APRON LENGTH/MASH, RIGHT	
808. REPAIR AND CORRECT DIAMOND CONDITION	

24	S01		RADIATOR SUPPORT						
25	S01	Remove/Replace	Upper tie bar	1	242.00T	OEM	0.6T	Body	0.6T
26	S01	Remove/Replace	Radiator support	1	279.00T	OEM	4.8T	Body	
27	S01	Remove/Replace	Hardware kit	1	17.60T	OEM			
28	S01	Remove/Replace	RT Support brace	1	48.00T	OEM	0.0T	Body	0.2T
29	S01		Add for Clear Coat						0.1T
30	S01	Remove/Replace	LT Support brace	1	48.00T	OEM	0.0T	Body	0.2T
31	S01		Add for Clear Coat						0.1T
32	S01	Repair	Crossmember				3.0T	Body	0.7T
33	S01		Overlap Minor Panel						(0.2)T
34	S01	Remove/Replace	RT Air deflector Town & Country	1	28.35T	OEM	0.0T	Body	
35	S01	Remove/Replace	LT Air deflector Town & Country	1	28.20T	OEM	0.0T	Body	
36	S01	Remove/Replace	Underbody shield	1	302.00T	OEM	0.0T	Body	
37	S01	Remove/Install	Splash guard				0.0T	Body	









Identify Associated Damage



- Determine damage to adjacent panels
 - Damage to flanges
 - Damage to inner panels












Corrosion Protection and Seam Sealers

- Align with repair area
 - Rear Body
 - Panel adhesive
 - Seam sealer
 - Weld thru primer
 - Quarter Panel
 - Seam sealer
 - Weld thru primer
 - Panel adhesive
 - Cavity Wax
 - Undercoating
 - Floor
 - Seam sealer
 - Weld thru primer
 - Doors
 - Panel adhesive
 - Seam Sealer
 - Intrusion beam foam
 - Cavity wax
 - Rockers
 - Cavity wax
 - Weld thru primer












Inspect Lighting and Wiring

- All lamp bulbs/harnesses should be inspected
 - Inspect all wiring harnesses for kinks/breaks





Identify any broken bulbs










Document Wiring Repair



- Identify number of wires broken
 - Indicate number of wires in line note
 - Add a parts line for connectors tape solder



Verify wiring repairs can be accomplished









Identify Mechanical Repairs

- Identify all parts requiring replacement
 - Identify associated repairs
 - Determine access labor
 - Account for vehicle condition
 - Consider attaching hardware



SPECIAL NOTATION:

The items listed below apply to all labor procedures.

- A/C System, Evacuate and Recharge
- Access to repair information/subscription cost
- Aftermarket & OEM accessories
- Alignment, straightening, or verifying the dimensional accuracy of related parts
- Alignment check of front or rear suspension/steering
- Anticorrosion material restoration/application
- Battery D&R/recharge
- Brackets & braces transfer
- · Broken glass removal or clean up
- Brakes, bleed and adjust
- Caulk (non-OEM), sound insulate or paint inner areas
- Clean up or detailing of vehicle prior to delivery
- Computer control module D&R/relearn
- Conversion Vans (special components, equipment and trim)
- Cutting, pulling or pushing collision damaged parts for access
- Damaged or defective replacement parts
- Drain & refill fuel tank
- Drilling, modification or fabrication of mounting holes
- Fabricate templates, reinforcing inserts, sleeves or flanges
- Filling, plugging and finishing of unneeded holes in new parts
- Information label installation
- Maintenance costs of building or equipment
- Material costs
- Pinch weld clamp damage repair
- Refinishing
- Repair information retrieval/lookup
- Reset electronic memory functions after battery disconnect
- Road test vehicle
- Rusted, frozen, broken or corrosion damaged components or fasteners
- Scan tool clear/reset electronic module
- Scan tool diagnostics
- Steering Angle Sensor recalibration
- Straighten or align used, reconditioned or non-OEM parts
- Structural damage diagnosis and vehicle set up time
- Structural foam removal or application
- Test for water leaks (except Windshield, Back Glass, and Stationary Glass)
- Test panel/spray caulk
- Trial-Fit of a component to verify dimensional accuracy of adjoining parts
- Undercoating, tar or grease removal
- Unprimed bumpers, removal of mold-release agents
- Waste disposal fees (all types)
- Weld through primer
- Welded seam surface finishing finer than 150 grit sandpaper
- Welder set-up or preparation
- Wheel or hub cap locks R&I









Document Mechanical Repairs

- Document all parts requiring replacement individually
 - Avoid "Right Front Suspension" as a line
 - Create line notes to describe damage
 - Four wheel alignment is a must

19	Repl	RT Strut	1	\$187.53	1.3	М
20		Note: Bent at control arm mount				
21	Repl	RT Lower control arm	1	\$ 58.50	.8	М
22		Note: Rolled at ball joint				
23	Repl	RT Lower ball joint	1	\$ 22.30	Incl	М
24	Repl	RT Outer tie rod	1	\$ 39.60	.6	М
25		Note: Bent at spindle attachment point				












Identify Interior Repairs

- Damage from secondary impact
 - Passengers
 - Cargo
 - Fluid spills
- Damage related to restraint systems















Validate Restraint System Repairs

Use websites to verify process

- OEM
- I-CAR
- AllData
- OEM1stop

PARTS THAT MUST BE REPLACED FOLLOWING A DEPLOYMENT When any deployable device or combination of devices have deployed and/or the Restraints Control Module (RCM) has DTC B1231/B1193:00 (Event Threshold Exceeded) in memory, the repair of the vehicle SRS is to include the removal of all deployed devices and the installation of new deployable devices, the removal and installation of new impact sensors and the removal and installation of a new RCM:

- Drivers side airbag (If Deployed) [AIRBAG, STEERING WHEEL]
- Passengers side airbag (If Deployed) [AIRBAG,INSTRUMENT PNL]
- Steering column (deployable column if equipped), (If Deployed)
- New impact sensors [AIRBAG SENSOR, FRONT; AIRBAG SENSOR, INTERIOR]
- Clockspring (when the driver air bag module has deployed)
- Restraints control module (RCM) [MODULE,AIRBAG CONTROL]
- Driver safety belt systems (including retractors, buckles and height adjusters), (If Deployed)
- Front outboard Passenger safety belt systems (including retractors, buckles and height adjusters), (If Deployed)
- Drivers side seat airbag (If Deployed) [AIRBAG,FRONT SEAT]
- Passengers seat side airbag (If Deployed) [AIRBAG,FRONT SEAT]
- If a side seat air bag deployment took place, the seatback pad, trim cover and side air bag module must be replaced. The seatback frame should be installed new if necessary.
- · Any damaged or defective restraint system part









Restraint Systems

BASF AUTOMOTIVE REFINISH COATINGS



Was a child seat in place

Restraint Considerations

- How many people were in the vehicle
 - Were occupants wearing seat belts
- Which seat belts were used












Identify Paint Type



- Locate Body Plate
- Determine Color
 - paintscratch.com
 - Solid Color
 - Pearl
 - Metallic
 - Tri Coat













Verify Refinish Requirements

Inquiry Details

Submission Information

Tracking #: 10051 Date Submitted: 11/07/2016 Status: Resolved (IP Change)

Inquiry Resolution

IP Explanation

Estimated Release Date: Closed Proposed Resolution: MOTOR stated:

4 stage colors may be developed as a 3Stage formula, 4Stage formula, or both 3Stage and 4Stage formulas depending on the paint manufacturer. In general a 4Stage formula will require the application of a ground coat in addition to the base coat and mid coat application while others may use a tinted clear coat in addition to the final clear coat (non-tinted). The use of a ground coat or tinted clear coat has not been considered in MOTOR's THREE-STAGE FINISHES (Base/Mica/Clear Coat) and is not included.

estimated refinish time:

- 1. Test spray-out panel or let down panel to match color.
- 2. Application of a tinted clear coat (only if it is in addition to the non-tinted clear coat)
- 3. Application of a ground coat (only if it is in addition to base coat and mid coat)
- 4. Sanding the tinted cleat coat or clear coat to match the texture of the adjacent panels.

 MOTOR suggests using an on-the-spot inspection for any additional refinish steps required for a 4Stage formula.

According to the Guide To Estimating, material costs are not included in any labor operation.

MOTOR will add the suggestion of developing a 4Stage formula or making revisions to the MOTOR Guide To Estimating REFINISHING PROCEDURES THREE-STAGE FINISHES (Base/Mica/Clear Coat) for its next scheduled review process.

No changes required.



- Determine Blend Requirements
- Determine multi-stage process
 - Base/clear
 - Three Stage
 - Four Stage
 - Ground coat requirements
- Determine partial paint times
 - Inner structures
 - Validate overlaps
- Identify items to be painted off of vehicle









Verify Refinish Requirements

- Validate Clear requirements
 - Don't rely on estimating system
 - Confirm with paint manufacturer



Clearcoat Blending

BASF recommends applying the specified amount of clear to the entire panel when doing basecoat/clearcoat repairs. This will make the repair eligible for the Glasurit or R-M lifetime warranties.

Blending the clearcoat requires that the thickness of clear be reduced in the blend area. This can result in the clearcoat blend-edge becoming visible after a period of exposure to sunlight and weather. The blend edge can also become visible if it is polished too aggressively.

For these reasons, BASF will not warrant the blended edges of clearcoats. Although, BASF has developed processes and products for blending clearcoats, these are intended as a cost-saving measure in those instances where an economical, non-warranty repair is required.

Detailed guidelines for applying clearcoats can be found in the Glasurit or R-M technical data sheets and technical reference manuals. These documents can also be found online at BASFrefinsh.com.









115 - REFINISH PROCESS: 643. DIFFICULT COLOR, TINTING & TESTING (INACCURATE VARIANCE) 644. MASK FOR PRIMING 645. SPOT PAINT CORESUPPORT AFTER INSTALLED (SECOND PAINT) 646. SPRAY OUT TEST PANEL 647. SPRAY OUT LET-DOWN PANEL FOR THREE STAGE 648. SPRAY OUT LET-DOWN PANEL FOR TRANSPARENT COLOR 649. COLOR TINT & TEST TO BLENDABLE MATCH 650. COLOR TINT SECOND COLOR 651. GRAVEL GUARD FIRST PANEL 652. GRAVEL GUARD SECOND PANEL 653. GRAVEL GUARD THIRD PANEL 654. GRAVEL GUARD SPRAY-OUT TEST PANEL 655. HAZARDOUS WASTE DISPOSAL 656. UNDERSIDE COLOR TINTING & TESTING (CORESUPPORT & TRUNK AREAS) 657. UNDERSIDE COLOR REFINISH 658. COVER VEHICLE (FOR REFINISHING ONE TIME) 659. REFINISHING JAMBS (SEPARATE COLOR THAN EXTERIOR-EACH COLOR*) 660. MASKING JAMBS

Document Refinish Process

- Itemize Blend Panels
 - "A" Pillar
 - Up and Over
- Document flex additive requirement
 - Align with panel refinished
- Identify rock guard needs
 - Align with panel refinished
- Document raw plastic preparation requirement
 - Use line notes to describe
- Identify items painted off vehicle









Identify Stripe Requirements

- Determine if OEM or Aftermarket
 - Use 3M chart to identify stripe
- Document stripe on estimate
 - Indicate stripe type to insure proper billing
 - Itemize stripe per panel



125 - STRIPES:

672. REMOVE OLD STRIPES WITH ERASER WHEEL USE

673. RESTRIPE WITH FINE-LINE TAPE

674. RESTRIPE PAINTED-ON

675. FACTORY STRIPE INSTALLATION













Fluid Requirements

20 - RADIATOR, AC AND FLUIDS:
114. REPAIR RADIATOR
115. REPAIR FAN SHROUD(S)
116. REPAIR AC CONDENSER/LINES
117. FLUSH LKQ CONDENSER/LINES
118. FLUSH LKQ RADIATOR/LINES
119. REPAIR AC LINES & TUBES
120. REPLACE RADIATOR "O"-RINGS **TRANS**
121. REPAIR TRANS COOLER/LINES
122. REPAIR WIRING/FASTENERS ATTACHED TO FAN SHROUDS
123. PRESSURE TEST COOLING SYSTEM
124. BLEED COOLING SYSTEM
125. TEST AC SYSTEM/CONTIMANITES
126. RECOVER AC FREON
127. EVACUATE & RECHARGE AC SYSTEM
128. TEST KIT REFRIGERANT RECOVERY
129. COOLANT, OEM RECOMMENDED PER GALLON
130. VACUUM FILL RADIATOR
131. TRANMISSION FLUID (PINT)
132. STEERING FLUID (PINT)
133. WINDSHIELD WASHER FLUID
134. R-134 FREON AND OIL (TWO POUNDS)
135. O-RING SEAL KIT FOR AC LINES

- Any fluids removed should be measured
 - Allows adequate replacement
 - Allows accurate billing
- Document Freon requirements
 - Avoid using blanket amount
- Identify replaced fluids within category used
 - Quantity should be annotated in a line note
- Identify OEM specific fluid requirements

















Tire Requirements



30 - WHEELS/TIRES/WHEEL ALIGNMENT:
168. REPLACE VALVE STEMS AND WEIGHTS
169. MOUNT & BALANCE TIRE
170. R&I WHEEL COVERS
171. TIRE DISPOSAL FEE
172. REPAIR RIM EDGE, POLISH SKUFF MARKS
173. ROTATE TIRES
174. RESET TIRE PRESSURE SENSORS
175. R&I WHEEL COVERS TO MOUNT ALIGNMENT HEADS
176. FOUR WHEEL ALIGNMENT
177. ECENTRIC ALIGNMENT KIT (PER SIDE)
178. INSPECT SUSPENSION COMPONENTS FOR DAMAGE

- Tire size and tread depth is noted in line note
 - Tire size and brand should be included in note
 - Tread depth measurement is annotated in line note
- TPMS Re-calibration
- Tire disposal fees
- Tire Tax











Final Photos



- Use repair plan as a checklist
 - Take photos in order of estimate
 - Label photos for clarification
 - Follow CIC Best Practice for Digital Imaging













Validate and Complete Estimate

- Verify all "Incl" labor
 - Conduct P-Page audit
 - When in doubt consult DEG

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	FRONT BUMPER	,					
2		O/H bumper assy				2.2	
3	Repl	Bumper cover	865112H000	1	261.44	Incl.	2.4
		Note: Component comes unprime	d from OEM. Preparation is r	equired.			
4		Add for Clear Coat					1.0
5	Repl	Prep unprimed bumper		1			0.6
6	# Repl	Flex additive		1	8.95 T		
7	Repl	Bumper grille	865612H001	1	52.58	Incl.	
		Note: LABOR: Time is after bump	er cover is removed. Time in	ncluded v	vith overhaul.		
		Chipped on outside upper corner					
8	Repl	Energy absorber	865202H000	1	73.00	Incl.	
9	Repl	RT Outer bracket	865142H000	1	23.89	Incl.	
		Note: LABOR: Time is after bump	er cover is removed. Time n	ot includ	ed in overhaul.		
10	#	RT Outer bracket labor		1		0.1	
		Note: System overrode labor: Tin	ne not included in overhaul.				

Inquiry Details

Submission Information

Date Submitted: 06/05/2019

Status: Resolved (IP Change)

Body: Sedan

Inquiry Resolution

Tracking #: 14200

Estimated UM Release Date: 07/01/2019

Proposed Resolution: MOTOR stated:

After review, in the Front Bumper group, Bumper & Components 2006-2008 subgroup, the estimated work time applied to the Reinforcement Beam has been updated to 0.4 hours from 2.0 hours. The footnote applied to the Reinforcement Beam has been updated and now states, "LABOR: Time is after bumper cover is removed. Time is not included in overhaul."

Vehicle Information

Year: 2006 Make: Acura Model: TSX

Database Inquiry

Inquiry Type: Procedure Page Issue

Database: CCC

Area of Vehicle: Front Bumper

Page #:

Issue Summary: The Impact Bar/Reinforcement is bolted to the Frame Rails on this model. Per the general P-Page section, an Impact Bar/Reinforcement is not Included if it bolts to the Frame Rails, however the specific note on the Impact Bar/Reinforcement says: "Time is for overhaul" & shows the same 2.0 hours as if you only select a Bumper Cover & Lower Valance. The Impact Bar is held onto the Frame Rails with 6 bolts. Also there is a weight mounting inside the Impact Bar with 2 nuts & the Ambient Air Sensor/bracket needs transferred as well.

Suggested Action: Correct the database to show .6 as a working time to Replace the Impact Bar/Reinforcement after the Bumper Cover is removed/Overhaul









91	#	Repl	REFRIGERANT R134	1	25.00		
92	#	Rpr	SET UP AND MEASURE			2.0	
93	#	Rpr	PULL MASH			3.0 F	
94	#	Rpr	PULL SWAY			1.0 F	
95	#	Subl	ALIGNMENT	1	89.95 X		
96	#	Repl	COROSION PROTECTION	1	8.00	0.3	
97	#	Repl	SEAM SEALER	1	25.00		
98	#	Repl	UNDERCOATING	1	12.00	0.5	
99	#	Repl	WELD THRU PRIMER	1	2.50		
100	#	Repl	COVER CAR	1	5.00	0.3	
101	#	Repl	FLEX ADDITIVE	1	8.00		
102	#	Rpr	MASK JAMBS			0.3	
103	#	Refn	CLEAR COAT				3.0
104	#	Repl	PAINT MATERIALS	1	492.80		
105	#	Repl	HAZARDOUS WASTE DISPOSAL	1	5.00		

- Add miscellaneous charges
 - Align within areas used
 - Cover Car
 - Hazardous waste

8	Repl	Replace door skin	FL34- 16202204-AE	1	\$148.65	4.5	3.2
9	Ref	Add for clear					1.2
10	Repl	Solid Rivet	W790376- S900	10			
11	Repl	Door skin adhesive	3M 08115	1	\$56.89	Incl	
12		Note: Door skin replacement requires 100% of 3M P/N 08115 tube to complete repair. Labor included in door skin					
13	Repl	Door intrusion beam adhesive	3M 04275	1	\$12.13	.3	
14		Note: Intrusion beam requires 30% of 3M P/N 04275 tube to complete repair					
15	Repl	Door seam sealer	3M 08323	1	\$45.51	Incl	
16		Note: Door requires 80% of 3M P/N 08323 to complete repair. Labor included in door skin					
17	Repl	Door cavity wax	3M 08852	1	\$17.85	.3	
18		Note: Door requires 25% of 3M P/N 08852 to complete repair					









Determine Reparability



- Research NADA Website
 - Indicate exact Make, Model and Trim
 - Indicate current mileage









Determine Reparability

BASE AUTOMOTIVE REFINISH COATINGS

Appraisal total divided by vehicle value as a percentage

Appraisal Total: \$8,695.50 divided by Vehicle Value: \$12,025.00

Repair Percentage of 72%












Recap

- Be Thorough Communicate the Repair
- Itemize all repairs
 - Be descriptive
 - Make line notes
- Take photos
 - Let them illustrate the repair
 - Label them



Document * Document * Document







> Estimating

> Tools

Documentation











Useful Websites

Alldata Collision www.alldata.com/collision

BASF Automotive Refinish www.basfrefinish.com

Collision Industry Conference <u>www.ciclink.com</u>

Collision Hub www.collisionhub.com

Database Enhancement Gateway <u>www.degweb.org</u>

I-CAR www.i-car.com

NADA Guides <u>www.nadaguides.com</u>

OEM1Stop - Position Statements <u>www.oem1stop.com</u>

Paintscratch - Paint Info www.Paintscratch.com

3M Sop's <u>www.3mcollision.com</u>



















Thank You!

John Shoemaker AAM, Business Development Manager Automotive Refinish Mobile: 248.763.4375 john.a.shoemaker@basf.com